


THE TED WILLIAMS "400" • SPINNING REEL OF CHAMPIONS




PARTS LIST FOR TED WILLIAMS "400" AND "401" SPINNING REELS

101-107	Reel case & Bushing	5.25	121	Slotted Nut	.50	142	Ball cage	.20
102-162-163	Rotating case	2.95	122	Rotating case nut	.26	143	Inner thrust washer	.20
103-114-125	Reel cover	1.26	123	Bushing retaining screw	.12	144	Elastic connecting link washer .10	
104-108-116-117-563	Handle-complete	1.80	127	Control cam spring	.25	147-160	Roller guide and bushing . .60	
105	Reverse Lever	.40	128	Control Lever Spring	.20	148	Pickup Ball	.60
106	Pinion Bronze Bushing	1.35	129	Rotating spring fixing screw .20		151	Right hand cam	.50
107	Spiral gear bushing	.60	130	Acting pin	.12	152	Ball bearings	.08
108	Joint Pin	.05	131	Connecting link screw	.12	153	Anti-Reverse lever	.25
109	Pinion	3.10	132	Left hand screw	.15	154	Anti-Reverse screw hand lever .10	
110-124-140-145	Stem complete	1.50	133	Inner clutch washer	.12	155	Anti-Reverse spring	.10
111	Connecting link	.60	134	Clutch spring	.12	156	Reverse Knob Screw	.30
112-164-165-169	Clutch Control Knob complete 1.40		135	External Clutch washer	.22	158	Spool complete	2.25
113	Lever	.40	136	Clutch retaining washer	.30	159	Spool trigger	.20
115	Cam Screw	.30	137	Spiral clutch spring	.20	160	Bushing for roller	.20
116	Handle Pivot	.40	138	Spool trigger spring	.12	166	Shouldered cam screw	.30
117	Handle Knob	.30	139	Spool trigger screw	.12	337	Nut for pick-up ball	.15
118	Anti Reverse Cam	.40	140	Felt washer for stem	.10	338	Manual Knob for pick-up ball .75	
119-126	Spiral Gear Assembly	5.10	141	Thrust washer	.22	563	Handle pivot bolt	.25

TED WILLIAMS, Inc., maintains a complete stock of parts for the "400." Only a minimum number of parts are required to keep the "400" in perfect operation. If the TED WILLIAMS "400" fails to function properly and local repair service is not available, the complete reel should be sent to TED WILLIAMS, Inc., by insured parcel post with a letter of instruction enclosed.

ANTIPES



SPARE SPOOLS — a spin-fisherman's must . . . for extra line and lines of different tests. Each . . . \$2.25

Ted Williams, Inc.

P. O. BOX 48-786

MIAMI 48, FLORIDA